ΚΔΟΔΝΤ

DOCTORING, CLEANING, FILTRATION

Split Doctor Bearing

Causes of bearing wear

The harsh environments created by the papermaking process can have a detrimental effect on bearings. Despite the technology used in today's materials, repair and replacement of bearings is one of the more common causes for machine downtime. Repair or replacement of worn cam follower bearings often requires the removal of levers and other interfering parts or, in some cases, removal of the entire doctor assembly. The result is excessive and unnecessary downtime.

The split doctor bearing solution

By splitting the housing and the contact block, the split doctor bearing solution offers improved doctor performance and less maintenance downtime for bearing-related issues. The design allows for the removal of the upper section of the housing and block to repair or replace the worn or damaged cam followers on-machine. The lower section remains in its pre-set position, and the repair is completed without disturbing blade angle or doctor alignment.

Split wiper seal

A split wiper seal on each end of the housing contacts the reciprocating shaft and keeps contaminants from entering the bearing housing. The shaft wiper seals can be replaced on-machine eliminating the need to slide the seals off the end of the journal.

Overview



Features

- Long-life, anti-friction bearing
- "On-machine" doctor maintenance
- Doctor setting and alignment retained
- Applicable for all doctoring positions
- All stainless steel construction

Benefits

- Improved uniformity of blade contact to the roll
- Improved blade life
- Reduced downtime
- Reduced sheet wrap potential
- Improved oscillator performance



Split housing with

cam roller bearings





Split journal block

Split wiper seal

www.kadant.com

Kadant is a global supplier of high-value, critical components and engineered systems used in process industries worldwide.

KADANT SOLUTIONS DIVISION 35 Sword Street Auburn, MA 01501 USA

Tel: +1 508-791-8171 Email: info@kadant.com

Split Doctor Bearing-1001 (US) 05/2019 **Replaces All Previous Versions** © 2019 Kadant Solutions Division

